Disclaimer: This document is an English translation of the Japanese original which is filed with the Tokyo Stock Exchange and is only for reference purposes. In case of any discrepancy between this translation and the Japanese original, the latter shall prevail.



November 9, 2023

To Whom It May Concern

Company name: HAZAMA ANDO CORPORATION

Representative: Representative Director and President Kazuhiko Kuniya

Tokyo Stock Exchange Prime Market Securities Code: 1719

Contact: General Manager, Eisuke Yamada

Corporate Communication Department

Phone: +81-3-3575-6094

## Occurrence of an Incident in Construction Work Underway

HAZAMA ANDO CORPORATION (the "Company") hereby announces an incident that occurred during the "Installation of a seawall (seawater pump room area section) and other construction works at Tokai No.2 Power Station" under construction by a joint venture with the Company as the representative.

The Company would like to offer its sincere apologies to the contractee and all other concerned parties for any inconvenience caused by the incident.

The Company will continue to investigate and examine the cause of the incident alongside the contractee, and take appropriate measures responsibly.

## 1. Outline of construction work

Name of construction work: Installation of a seawall (seawater pump room area section) and other

construction works at Tokai No.2 Power Plant

Contractee: The Japan Atomic Power Company

Constructor: Joint venture by HAZAMA ANDO CORPORATION, PENTA-OCEAN

CONSTRUCTION CO., LTD., and WAKACHIKU CONSTRUCTION CO.,

LTD.

Construction site: Tokai-mura, Naka-gun, Ibaraki Prefecture

## 2. Incident that occurred

In June 2023, during foundation work on the south side of the seawall (steel guard wall) to be installed above an intake that pumps seawater to the Power Plant, some defects such as unfilled concrete and deformation of reinforcing steel were found in a part of the wall surface of the underground diaphragm wall. In the course of the investigation and verification of the incident, a similar situation was also noted for foundation work on the north side of the steel guard wall.

## 3. Current situation and measures to be taken in the future

After becoming aware of the incident, the Company has suspended the construction work of the steel guard wall and instituted the investigation and examination to determine the cause of the incident in cooperation with the contractee, which is still ongoing. The Company will take appropriate measures responsibly, such as by developing appropriate repair/reinforcement plans based on the results of the investigation and examination.

4.	Impact on the Company's business results
	Should it become clear that there will be a significant impact on the Company's consolidated financial results
	forecast in the future, the Company will disclose it in a timely and appropriate manner.